



468116

Handwritten initials/signature

POTENTIAL GROUND WATER CONTAMINATION SOURCE

IDENTIFICATION AND PRELIMINARY ASSESSMENT

This form is completed for each potential hazardous waste site to help set priorities for site inspections. The information submitted on this form is based on available records and may be updated on subsequent forms as a result of additional inquiries and on-site inspections. If information is not available, place an "x" in the space provided.

SITE IDENTIFICATION

COMPANY NAME SANDELL Inc. } 5074
MAL Enterprises #3 } Asmes used!

ADDRESS 1805 HAMLIN FOR RHE

LOCATION (COUNTY, TOWN & RANGE) S-24, AVON TWP. OAKLAND CO

OWNER/OPERATOR John Spokowski, MGR

HOW LONG HAS THIS FACILITY BEEN OPERATING AT THIS SITE? 1971? int. m. t. g.

HAS THERE EVER BEEN AN OWNERSHIP TRANSFER? unknown All Operati

IF SO WHEN? _____

PREVIOUS OWNER? _____

OPERATION CHARACTERIZATION

TYPE OF OPERATION (I.E. MANUFACTURING, LANDFILL, ETC.) Land fill

WASTE CHARACTERIZATION

Waste type:

Unknown Liquid Solid Sludge Gas

Waste characteristics:

Unknown Corrosive Ignitable Radioactive Highly Volatile

Toxic Reactive Inert Flammable

Other Specify _____

Waste description (metal sludges, PCB's, etc.) Construction debris, Steel
& general refuse,

PROBLEM CHARACTERIZATION (I.E. UNLINED SEEPAGE LAGOON, IMPROPER BARREL DISPOSAL,

ETC. "dealing with reported pollution of domestic wells along
Parks Street in Avon Twp" - area study re: in in 3/12 (no copy)
Not certain if bottom of landfill has a continuous clay layer. The landfill
below the water table

LIST ALL APPLICABLE PERMITS HELD BY THE SITE (FILL IN DATE OF ISSUANCE & PERMIT
NUMBER)

NPDES _____ Liquid industrial waste _____
Air _____ Groundwater discharge _____
Solid waste 3799 Exp. 11/4/75 Soil & sedimentation _____
Inland lakes _____ Other (specify) _____

COMPLIANCE HISTORY appears good.

CONTAMINATION INFORMATION

HAS THERE BEEN ANY ATTEMPT TO MONITOR THE GROUNDWATER IN THE PAST yes.

If so, give the location or identification number of the wells observation we
noted around perimeter of site on site map

List any pertinent monitoring data (include date and laboratory used for
analysis no results of any analysis seen in file. A letter
of 3/2/76 to Spokooski from Kellow mentions a "groundwater
contamination study." Said study not in file. The study
supposedly suspects the landfills in the area.

GIVE THE LOCATION & DISTANCE TO THE NEAREST PRIVATE WELL unknown

GIVE THE SOURCE OF MUNICIPAL WATER SUPPLY _____

LIST ANY KNOWN GEOLOGICAL CHARACTERISTICS OF THE AREA sand over blue
clay

DEPARTMENT ACTION

HISTORY OF SITE INSPECTIONS (LIST DATE, INSPECTING AGENCY & RESULTS) 10/31/78 SA
site is not being used. 2/2/78 material final cover. (units
on site inspection by Kellum/Boek on 11/29/76) & repairs
need for changes.

REGULATORY ACTIONS (NOTICES OF NONCOMPLIANCE & VIOLATIONS, DATES & REASONS)

REMEDIAL ACTIONS REQUESTED (ACTIONS & DATES) Construction and cleanup
at strategic sites

Were these actions accomplished? evidently

Case name Sand fill #3, Oakland Co

Date 11-20-79

PRELIMINARY PROBLEM ASSESSMENT

POTENTIAL HAZARDS (CHECK ALL APPLICABLE CATEGORIES)

- Human health Noticeable odors
- Contamination of water supply Contamination of soils
- Contamination of groundwater Property damage
- Contamination of surface water Sewer/storm drain problems
- Contamination of food chain Erosion problems
- Damage to flora/fauna Inadequate security
- Fish kill Other (specify)
- Contamination of air
- Fire or explosion
- Spills/leaking containers (runoff) standing liquids
- Incompatible wastes
- Midnight dumping

WHAT ADDITIONAL INFORMATION IS REQUIRED? Present contamination condition - groundwater quality info.
need groundwater study of area referred to in file
have monitoring wells been installed? sanded?

DESCRIBE ANY NECESSARY ACTIONS WHICH SHOULD BE UNDERTAKEN? (ADDITIONAL SAMPLING, SITE INSPECTION, ETC.) regular monitoring of monitoring wells

